

Item Wise BoQ

Name of Work: Repairing of BL147TH Tyre Handler SI. No H98 with following works : (1) Dismounting of lift arm assembly and repairing it by cleaning, grinding, welding with suitable electrodes and line boring and making of 02 nos. steel bush and pin at lift arm foot and 02 nos at front chassis link with lift arm along with its fitment and locking.(2) Repairing of the right clamp, tilt cylinders with providing new repair kits.

Contract No:

Name of the Bidder/ Bidding Firm / Company :												
PRICE SCHEDULE (This BOQ template must not be modified/replaced by the bidder and the same should be uploaded after filling the relevant columns, else the bidder is liable to be rejected for this tender. Bidders are allowed to enter the Bidder Name and Values only)												
NUMBER #	TEXT #	TEXT #	NUMBER #	TEXT #	NUMBER	NUMBER #	NUMBER	NUMBER	NUMBER #	NUMBER #	NUMBER #	TEXT #
SL No.	Item Description	Item Code / Make	Quantity	Units	Estimated Rate in Rs. P	BASIC RATE in Figures To be entered by the Bidder in Rs. P	GST (If applicable in Percentage)	GST Amount in Rs. P	HSN / SAC Code	TOTAL AMOUNT excluding taxes in Rs. P	TOTAL AMOUNT including taxes Rs. P	TOTAL AMOUNT In Words
1	2	3	4	5	6	7	8	9	10	11	12	13
1	Repairing of lift arm assembly & tilt cylinder											
1.01	Steel electrodes	item1	28.00	kg			18.00	0.00		0.00	0.00	INR Zero Only
1.02	Gauging electrodes	item2	20.00	kg			18.00	0.00		0.00	0.00	INR Zero Only
1.03	Gas Charges	item3	3.00	No			18.00	0.00		0.00	0.00	INR Zero Only
1.04	Machinable electrodes	item4	35.00	kg			18.00	0.00		0.00	0.00	INR Zero Only
1.05	Grinding machine cost	item5	8.00	SFT			18.00	0.00		0.00	0.00	INR Zero Only
1.06	Grinding wheel cost	item6	8.00	No			18.00	0.00		0.00	0.00	INR Zero Only
1.07	Tilt cylinder repair kit (PN 349112460000)	item7	1.00	No			18.00	0.00		0.00	0.00	INR Zero Only
1.08	Clamp cylinder repair kit (PN 349112900000)	item8	1.00	No			18.00	0.00		0.00	0.00	INR Zero Only
1.09	Replacement of rusted plate, bolts and washer	item9	1.00	Set			18.00	0.00		0.00	0.00	INR Zero Only
1.1	02 nos steel bush making (PN 355L111062)	item10	2.00	No			18.00	0.00		0.00	0.00	INR Zero Only
1.11	02 nos steel bush making (PN 355L111079)	item11	2.00	No			18.00	0.00		0.00	0.00	INR Zero Only
1.12	02 nos pin rebuilding(PN 35L02063)	item12	2.00	No			18.00	0.00		0.00	0.00	INR Zero Only
1.13	02 nos pin rebuilding(PN 349110000002)	item13	2.00	No			18.00	0.00		0.00	0.00	INR Zero Only
1.14	Hyd. Jack, jigs and fixture and vehicle charges	item14	5.00	Days			18.00	0.00		0.00	0.00	INR Zero Only
1.15	Line boring setup charges	item15	4.00	Days			18.00	0.00		0.00	0.00	INR Zero Only
1.16	Lathe Machining charges	item16	3.00	Days			18.00	0.00		0.00	0.00	INR Zero Only
1.17	Skilled welder 02 nos X 02 shift X 05 days	item17	20.00	SFT			18.00	0.00		0.00	0.00	INR Zero Only
1.18	Skilled fitter 02 nos X 02 shift X 05 days	item18	20.00	SFT			18.00	0.00		0.00	0.00	INR Zero Only
1.19	Semi-Skilled fitter 01 nos X 02 shift X 02 days	item19	4.00	SFT			18.00	0.00		0.00	0.00	INR Zero Only
1.2	Helper 02 nos X 02 shift X 05 days	item20	20.00	SFT			18.00	0.00		0.00	0.00	INR Zero Only
1.21	Supervisor 01 nos X 02 shift X 05 days	item21	10.00	SFT			18.00	0.00		0.00	0.00	INR Zero Only
Total in Figures										0.00	0.00	INR Zero Only
Quoted Rate in Words									INR Zero Only			

1	Constructi item1	10	1	Nos
1.01	Supplying item1	123.223	Nos	
1.02	Constructi item2	213	Nos	
1.02	Constructi item2	213	Nos	
1.01	Supplying item1	123.223	Nos	
1.02	Constructi item2	213	Nos	
1.02	Constructi item2	213	Nos	
1.01	Supplying item1	123.223	Nos	
1.02	Constructi item2	213	Nos	
1.02	Constructi item2	213	Nos	
1.01	Supplying item1	123.223	Nos	
1.02	Constructi item2	213	Nos	
1.02	Constructi item2	213	Nos	
1.02	Constructi item2	213	Nos	
1.01	Supplying item1	123.223	Nos	
1.02	Constructi item2	213	Nos	
1.02	Constructi item2	213	Nos	
1.01	Supplying item1	123.223	Nos	
1.02	Constructi item2	213	Nos	
1.02	Constructi item2	213	Nos	
1.01	Supplying item1	123.223	Nos	
1.02	Constructi item2	213	Nos	
4	Constructi item5	10	Nos	