agaor (CP)/Kedlal Washery. aliring of fuel Injector pump, radiator, alternator & se la Washery. der/HEMM/25-26/48 date:-30.09.2025 eggory of Services (To Be Selected by Department) Works Contract	If boom cylinde	or and cooling system of Hydrauli Category of Bidder (To Be Selected by Bidder)	c Excavator make-BEML Model BE NIT No-	E200-1, Sl. No. 10083 at PO/KW/E-		
lla Washery. der/HEMM/25-26/48 date:-30.09.2025 egory of Services (To Be Selected by Department)	olf boom cylinde		c Excavator make-BEML Model BE NIT No-	E200-1, SI. No. 10083 at PO/KW/E-		
der/HEMM/25-2648 date:-30.09.2025 eggory of Services (To Be Selected by Department)		Category of Bidder	NIT No-	PO/KW/E-		
		Category of Bidder				
Works Contract		(To Be Selected by Bidder)	To Be Entered by Department			
	lable Works Contract the Bidder/ Firm /		Rate of GST (in %)	Total GST(in Rs.)	GST to be Paid By Bidder (in Rs.)	GST to be Paid By CIL/Subsidiary (in Rs.)
1		Select	18	0.00	0.00	0.0
ate must not be modified/replaced by the bidder and	the same shoul	Poster in the property of the	RICE SCHEDULE event columns, else the bidder is l	liable to be rejected for th	nis tender. Bidders are allowed to	enter the Bidder Name and Values only)
TEXT#	NUMBER #	TEXT #	NUMBER	NUMBER#	NUMBER #	TEXT#
Item Description	Quantity	Units	Estimated Rate in		TOTAL AMOUNT Without Taxes	
			Rs. P	Figures To be entered by the Bidder in Rs. P	in Rs. P	In Words
2	3	4	5	6	7	8
ator Repairig:- of bracket	2.00	Nos.				INR Zero Only
& bottom Changing	2.00	Nos.				INR Zero Only
of new Jali of radiator.	1.00	No.			0.00	
k-up of fuel pump:- tel element changing.	6.00	Nee			0.00	INR Zero Only
p element changing	6.00				0.00	INR Zero Only
pump assembly	1.00					INR Zero Only
Vheel	1.00					INR Zero Only
p kit	1.00					INR Zero Only
d primer v. Bearing	1.00	No.				INR Zero Only INR Zero Only
ilter outer & inner	1.00	No.				INR Zero Only
raulic hose pump	4.00	Nos.				INR Zero Only
rhauling & testing of fuel pump.	1.00	No.			0.00	
airing of self & alternator	1.00	No.			0.00	
n Cylinder:- airing of eyes of strik cylinder & supply of gun metal bushes	2.000	Nos.				INR Zero Only
acement of threaded portion of cylinder by machining.	2.000	Nos.				INR Zero Only
hing & buffering of piston rod of boom cylinder	2.000	Nos.				INR Zero Only
acement of seal kit 781HC03061	2.000	Nos.				INR Zero Only
acement of H. T. bolt	24.000	Nos.				INR Zero Only
	4.000	Nos.				INR Zero Only
hing of barrels	2.000	Nos.				INR Zero Only
ing system:- raulic cooler repairing	1 000	No.			0.00	INR Zero Only
er pump new changing		No.			0.00	INR Zero Only
ng repairing & cooling relay changing	1.000	No.			0.00	INR Zero Only
nging of bearing & repairing of housing part no. 7818HS					0.00	INR Zero Only
		No.			0.00	INR Zero Only
raulic cylinder & Arm cylinder:- airing of eyes stick cylinder with mounting & fitting of GM	1.000	No.				INR Zero Only
nes. acement seal kit of Arm cylinder part no. 781HC030861	2.000	Nos.			0.00	INR Zero Only
airing of thread portion of cylinder by machining	2.000	Nos.			0.00	INR Zero Only
		Nos.				INR Zero Only
						INR Zero Only
**						INR Zero Only
ly Skilled-2X9					0.00	INR Zero Only
i-Skilled 2X9	18.000	Shift				INR Zero Only
skilled- 4X9						INR Zero Only INR Zero Only
	1.000	No.		0.00		
- In-particular and particular of the	1.00			3.00		
					0.00	INR Zero Only
I				INR Zero Only		I .
acei acei ihing iling rauli er p ng r ngin 78 acei airin ies. acei airin ies. acei ishing ishing ishing iskille it	ment of seal kit 7814C03061 ment of H. T. bolt ment of H. T. bolt ment of Archev nut g of barrels system: (cooler repaining pump new changing pump new changing g of bearing & repairing of housing part no. 7818HS ement of seal kit part no. 7818HS g of eyes stick-cylinder with mounting & fitting of GM ment seal kit of Arm cylinder part no. 781HC030861 g of thread portion of cylinder by machining g & buffering of piston rods. semenby part no. 781H9 1013 charge-Supervision- 1X9	ment of Seal kit 781HC03061 2.000 ment of N. T. Dolt 24,000 ment of N. T. Dolt 24,000 ment of Check nut 4.000 go of barries 2.000 go of barries 2.000 mount of Check nut 4.000 go of barries 3.0000 mount of Check nut 4.000 mount of Check nut 4.000 mount of Check nut 4.0000 mount seal kit part no. 781H5 96686 1.000 1.0000 mount seal kit of Arm cylinder- 2.0000 mount seal kit of Arm cylinder with mounting & fitting of GM 2.0000 mount seal kit of Arm cylinder with mounting & fitting of GM 2.0000 mount seal kit of Arm cylinder part no. 781HC030861 2.0000 mount seal kit of Arm cylinder by machining 2.0000 go for thread portion of cylinder by machining 2.0000 go for thread portion of cylinder by machining 2.0000 seably part no. 781PH 91023 2.0000 charges- Supervision- 1X9 9.0000 milled 2X9 18.0000 sed-4X9 3.60000 1.000	2.000 Nos.	ment of Seal Nt 781HC03061 2.000 Nos. ment of Nt. T. bolt 24.000 Nos. ment of Check nut 4.000 Nos. ment of Check nut 4.000 Nos. go d'barreis 2.000 Nos. system: (c cooler repairing 1.000 Nos. (c cooler repairing 1.000 No. may new changing 1.000 No. (a cooler repairing 6.000 Nos. (b cooler repairing 6.000 Nos. (c c c c c c c c c c c c c c c c c c c	2,000 Nos.	ment of Seal kit 7811C03061 2,000 Nos. 0.00 ment of H. T. bolt 2,000 Nos. 0.00 ment of H. T. bolt 2,000 Nos. 0.00 ment of H. T. bolt 0,000 ment of