Tender Inviting Authority: Staff officer(E&M), Dhori Area.									
	.,								
Name of the Work / Contract No:	Complete repairing and full overhauling of two nos. 2000 GPM 10/12, Pluro 3CHRS and Pluro X 2CHRS, 150 m head, Mi assemblies required for mine dewatering considering upcoming monsoon season 2024 in respect of AADOCM, Dhori A			istage pump					
	Category of Services (To Be Selected by Department)		Category of Bidder (To Be Selected by Bidder)	To Be Entered by Department					
ITC Available	Works Contract		Bidder's Status (Mandato ry)	Rate of GST (in %)	Total GST(in Rs.)	GST to be Paid By Bidder (in Rs.)	GST to be Paid By CIL/Subsidiary (in Rs.)		
Name of the Bidder/ Bidding Firm / Company :			Select	18	0.00	0.00	0.0		
PRICE SCHEDULE (This BOQ template must not be modified/replaced by the bidder and the same should be uploaded after filling the relevent columns, else the bidder is liable to be rejected for this tender. Bidders are allowed to enter the Bidder Name and Values only)									
NUMBER #	TEXT #	NUMBER #	TEXT #	NUMBER	NUMBER #	NUMBER#	TEXT #		
SI. No.	Item Description	Quantity	Units	Estimated Rate in Rs. P	BASIC RATE In Figures To be entered by the Bidder in Rs. P	TOTAL AMOUNT Without Taxes in Rs. P	TOTAL AMOUNT In Words		
1	2	3	4	5	6	7	8		
1.01	Pump shaft repairing by both side damaged and worn- out bearing seat welding, machining, alignment checking, straightening, polishing	2	Nos.				INR Zero Only		
1.02	Check nut & lock nut new for shaft sleeve.	4	Nos.				INR Zero Only		
1.03	Heavy duty key making for Impellers & balancer.	6	Nos.			0.00	INR Zero Only		
1.04	C.I. Casting shaft sleeve new for suction side.	2	Nos.				INR Zero Only		
1.05	C.I. Casting shaft sleeve new for delivery side.	2	Nos.				INR Zero Only		
1.06	Impellers repairing with the help of metal filling, jointing, both side colors, face and bore brass buildup and machining as per std size.	. 5	Nos.				INR Zero Only		
1.07	Cast Iron casting over size neck ring new.	7	Nos.				INR Zero Only		
1.08	Cast Iron casting over size neck bush new.	5	Nos.				INR Zero Only		
1.09	C.I Casting diffuser new making for suction body.	2	Nos.				INR Zero Only		
1.1	Old neck rings and neck bush cutting and new neck ring fitting with drilling, tapping and fixing CSK head screw.	12	Nos.				INR Zero Only		
1.11	Chamber & diffuser neck ring & neck bush seat true cut machining on lathe machine & alignment.	12	Seat				INR Zero Only		
1.12	Chamber & diffuser locking and fixing with each other & alignment.	5	Body				INR Zero Only		
1.13	C.I Casting balancer seat & disc new making casting, machining, drilling, tapping.	4	Nos				INR Zero Only		
1.14	Pump repair kit new provide like as chamber body "O" rings, "O" rings for long bushes, water deflector, rubber joint packing kite, test cork, gland bye pass pipe line, oil rings, bearing cover bolts, gland bolts, taping & threading in bodies.	2	Set			0.00	INR Zero Only		
1.15	Gun metal casting bush bearing new making as per sample with casting, machining, grooving and Cutting in two pieces as required.	4	Set			0.00	INR Zero Only		
1.16	Complete pump assembly dismantling by hydraulic press machine, Puller & re-fitting / assembling after repairing	2	Set			0.00	INR Zero Only		
1.17	Complete pump body rust & dust cleaning and body painting.	2	Nos.			0.00	INR Zero Only		
1.18	Transportation charges.	2	Nos.			0.00	INR Zero Only		
1.19	12" Finish size C.I Casting coupling new making with casting and machining for above pumps	2	Nos.			0.00	INR Zero Only		
2	Total impact of GST for the purpose of CTC	1.000	Nos		0.00		INR Zero Only		
Total in Figures						0.00	INR Zero Only		
Quoted Rate in Words				INR Zero Only					