

Name of the Work – Maintenance and repairing at site for 03 nos. 2MVA,01 no. 2.5 MVA & 250 KVA transformer with buchloz relay alarm bell system of Power transformer at RWP under Rajrappa Area.

ITC Available

SI .No	Description	Quantity	Units	Rate
1	Cost of winding temperature meter with Smtr cable for tripping device system. (22256.00-3394.98 18861.02)	4	NO	
2	Cost of Breather (11800.00-1800.00-10000.00)	4	NO	
3	Cork Sheet (1843.00-281.14-1561.86)	8	NO	
4	Cost of Buchloz Relay contact (22310.00-3403.22-18906.78)	4	NO	
5	Cost of Electronic Hooter (4200.00-640.68-3559.32)	1	NO	
6	Cost of HV Bushing with studs (15000.00-2288.14-12711.86)	4	NO	
7	Oil Filtration of Transformers	14500	LTR	
8	Wiring with ferruls & Lugs as required. (A)Cost of 2.5 sq mm PVC wire 24 Mtr X 36 44-874.56 (11) Cost of Ferruls (A to 2.0 to 9) (409.00 Lss GST @ 18% 62.38-346 62) 1 Set X 346 62-346.62 (C.)Cost of Luggs (0 to 2.5 sq mm) 16 Nos X 4.11-65.76 (D) Cost of PVC tap (RY, B) 2 Roll X 114.00-228.00	4	NO	
9	Cost of Cable 4core x 2.5sq mm, 1.1KV (Copper)	100	MTR	
10	Labour cost	1	no	
11	Contractor profit	1	no	
12	Total impact of gst	1	no	
13	Total	1	no	