

Name of the Work – Repairing of rear differential Axle Assy. for Payloader BL200-1 Sl. no. 10164 at Rajrappa Washery Project, Rajrappa Area.

ITC Available

Sl .No	Description	Quantity	Units	Rate
1	Differential Tail Pinion 376 AX 91153	1	nos	
2	Differential Crown Pinion 376 AX 91089	1	nos	
3	Bibble small pinion 376 AX 91097	4	nos.	
4	Bibble big pinion 376 AX 91064	2	nos.	
5	Bibble body 376 AX 91048,91112	1	nos.	
6	Tail bearing 376 AX 91201,91194	2	nos.	
7	Crown bearing 376 AX 91015	2	nos.	
8	Cross shaft 376 AX 91104	1	nos.	
9	Propeller shaft 376 pz 02036	3	nos.	
10	Cover 376 AX 91023	2	nos.	
11	Planet gear wheel 376 AX 91364	3	nos.	
12	Ring gear 376 AX 91323	1	nos.	
13	All material dismantling and fitting	1	nos.	
14	Total impact of gst	1	no	
15	Total	1	no	