

Validate Print Help		Item Rate BoQ					
Tender Inviting Authority:- Project Engineer (Excv), GVP Ph-II OCP, Kathara Area.							
Name of the Work / Contract No:-	Repairing of 2 nos. propel motor, 2 nos. rotary motors and 1 no. PTO power of RECP-650 Drill Sl. No. 6021401 of GVP Ph II OCP. NIT No. P.E(X)/GVP Ph-II/E-TENDER/25-26/44						
.	Category of Services (To Be Selected by Department)		Category of Bidder (To Be Selected by Bidder)	To Be Entered by Bidder			
ITC Available	Works Contract	Bidder's Status (Mandatory)	Rate of GST (in %)	Total GST(in Rs.)	GST to be Paid By Bidder (in Rs.)	GST to be Paid By CIL/Subsidiary (in Rs.)	
Name of the Bidder/ Bidding Firm / Company :		Select	18	0.00	0.00	0.00	
PRICE SCHEDULE (This BOQ template must not be modified/replaced by the bidder and the same should be uploaded after filling the relevent columns, else the bidder is liable to be rejected for this tender. Bidders are allowed to enter the Bidder Name and Values only)							
NUMBER #	TEXT #	NUMBER #	TEXT #	NUMBER	NUMBER #	NUMBER #	TEXT #
Sl. No.	Item Description	Quantity	Units	Estimated Rate in Rs. P	BASIC RATE In Figures To be entered by the Bidder in Rs. P	TOTAL AMOUNT Without Taxes in Rs. P	TOTAL AMOUNT In Words
1	2	3	4	5	6	7	8
2	(A) Repairing 02 nos. propel motors. Repairing worn out swas plate by cleaning, polishing for proper size.	2	nos.			0.00	INR Zero Only
3	Repairing of pin by welding and machining for proper size.	2	nos.			0.00	INR Zero Only
4	Repairing of head by welding and polishing for for proper size.	2	nos.			0.00	INR Zero Only
5	Repairing of rotor and piston by polishing, lapping and ring replacement.	2	nos.			0.00	INR Zero Only
6	Repairing of shaft by welding and machining	2	nos.			0.00	INR Zero Only
7	Repairing of relive valve	4	nos.			0.00	INR Zero Only
8	Repairing of check valve by replacement of seal kit	4	nos.			0.00	INR Zero Only
9	Dismantling and assembling of final drive and DC valve after cleaning and 'O' ring replacement.	2	set			0.00	INR Zero Only

10	(B) Repairing 02 nos. rotary motors. Repairing worn out swas plate by cleaning, polishing for proper size.	2	nos.			0.00	INR Zero Only
11	Repairing of pin by welding and machining for proper size.	2	nos.			0.00	INR Zero Only
12	Repairing of head by welding and polishing for for proper size.	2	nos.			0.00	INR Zero Only
13	Repairing of rotor and piston by polishing, lapping and ring replacement.	2	nos.			0.00	INR Zero Only
14	Repairing of shaft by welding and machining	2	nos.			0.00	INR Zero Only
15	Repairing of check valve by replacement of seal kit	2	nos.			0.00	INR Zero Only
16	(C) Repairing of pinion of PTO includidg welding and machining etc.	1	no.			0.00	INR Zero Only
17	Total impact of GST for the purpose of CTC	1.000	Nos		0.00	0.00	INR Zero Only
Total in Figures						0.00	INR Zero Only
Quoted Rate in Words		INR Zero Only					