**Item Rate BoQ** 

Tender Inviting Authority: Staff Officer (Excv), Dhori Area

Help

Name of the Work / Contract No: Repairing of main arm mounting bracket and blade support arm/cross arm, rep. of track frame, rep. of engine and radiator guard, rep. of idler assy. on both sides of Dozer SI No. 104859 and Rep. of cutting blade of Motor Grader SI No. M.G.3111.

|  | Category of Services (To Be Selected by Departmen  | nt)             | Category of Bidder<br>( To Be Selected by Bidder) | To Be Entered by Department                        |   |                                   |   |
|--|--|-----------------|---|--|---|-----------------------------------|---|
| TC Available                                       | Works Contract   |                 | Bidder's Status (Mandatory)                       | Rate of GST (in %)                                 | Total GST(in Rs.)   | GST to be Paid By Bidder (in Rs.) | GST to be Paid By CIL/Subsidiary (in Rs.) |
| Name of the Bidder/<br>Bidding Firm /<br>Company : |  |                 | Select  | 18   | 0.00  | 0.00                              | 0.00                                      |
| (This BOQ tem                                      | plate must not be modified/replaced by the bidder and                                    | d the same shou |   | PRICE SCHEDULE elevent columns, else the bidder is | liable to be rejected for   | this tender. Bidders are allowed  | to enter the Bidder Name and Values only) |
| NUMBER #   | TEXT #   | NUMBER #        | TEXT #  | NUMBER   | NUMBER #  | NUMBER #                          | TEXT #                                    |
| SI.<br>No.   | Item Description   | Quantity        | Units   | Estimated Rate in<br>Rs. P                         | BASIC RATE In<br>Figures To be entered<br>by the Bidder in<br>Rs. P |                                   | TOTAL AMOUNT<br>In Words                  |
| 1  | 2  | 3               | 4   | 5  | 6   | 7                                 | 8   |
| 1  | Item Description/ Heading  |                 |   |  |   |                                   |   |
| 1.01   | Repairing/welding of main arm mounting bracket and blade support arm/cross arm both side | 1.000           | Job   | 126670.00  |   | 0.00                              | INR Zero Only                             |
| 1.02   | Rep. of track frame bith side  | 1.000           | Job   | 124190.00  |   | 0.00                              | INR Zero Only                             |
| 1.03   | Rep. of engine and radiator guard  | 1.000           | Job   | 10907.00   |   | 0.00                              | INR Zero Only                             |
| 1.04   | Rep. of idler assy. on both sides both side  | 1.000           | Job   | 55256.00   |   | 0.00                              | INR Zero Only                             |
| 1.05   | Rep. of cutting edge end bit both side   | 1.000           | Job   | 103736.00  |   | 0.00                              | INR Zero Only                             |
| 1.06   | Rep. of cutting blade of motor grader  | 1.000           | Job   | 50417.00   |   | 0.00                              | INR Zero Only                             |
| 2  | Total impact of GST for the purpose of CTC   | 1.000           | Nos   |  | 0.00  |                                   | INR Zero Only                             |
| Total in Figures                                   |  |                 |   |  |   | 0.00                              | INR Zero Only                             |
| Quoted Rate in Words                               |  |                 |   |  |   |                                   |   |